



# THESE CEMA SAFETY LABELS CAN HELP MAKE YOUR CONVEYING EQUIPMENT OPERATIONS SAFER

**WARNING**  
Exposed moving parts can cause severe injury  
**LOCK OUT POWER** before removing guard

CHR930001 <http://www.cemanet.org>

CHR930001

CHS930001

**CAUTION**  
Do not enter  
Hazardous Area  
Authorized personnel only

CHR930006 <http://www.cemanet.org>

CHR930006

**WARNING**  
Exposed screw and moving parts can cause severe injury  
**LOCK OUT POWER** before removing cover or servicing

CHR930011 <http://www.cemanet.org>

CHR930011

**DANGER**  
Moving parts will cause severe injury  
**KEEP AWAY**

CHS950017 <http://www.cemanet.org>

CHS950017

**WARNING**  
Equipment starts automatically - can cause severe injury  
**KEEP AWAY**

CHR930002 <http://www.cemanet.org>

CHR930002

CHR930002 - W

**CAUTION**  
Low Clearance  
• Be Alert

CHR930007 <http://www.cemanet.org>

CHR930007

**WARNING**  
Exposed moving parts can cause severe injury  
**LOCKOUT POWER** before servicing

CHS950013 <http://www.cemanet.org>

CHS950013

**CAUTION**  
HOT SURFACE  
Contact with skin may cause burns  
**DO NOT TOUCH**

CHS950018 <http://www.cemanet.org>

CHS950018

**DANGER**  
Hazardous voltage will cause severe injury or death  
**LOCK OUT POWER** before servicing

CHR930003 <http://www.cemanet.org>

CHR930003

**CAUTION**  
Trip Hazard  
• Be Alert  
• Watch your step

CHR930008 <http://www.cemanet.org>

CHR930008

**CAUTION**  
Hazardous noise level  
Ear protection required in this area

CHS950014 <http://www.cemanet.org>

CHS950014

**WARNING**  
Exposed moving parts can cause severe injury  
**LOCK OUT POWER** before servicing

CHS950021 <http://www.cemanet.org>

CHS950021

**DANGER**  
Climbing, sitting, walking or riding on conveyor at any time will cause severe injury or death  
**KEEP OFF**

CHR930004 <http://www.cemanet.org>

CHR930004

CHR930004 - W

**WARNING**  
Servicing moving or energized equipment can cause severe injury  
**LOCK OUT POWER** before servicing

CHR930009 <http://www.cemanet.org>

CHR930009

**CAUTION**  
Hazardous environment  
Respiratory protection required  
Authorized personnel only

CHS950015 <http://www.cemanet.org>

CHS950015

**WARNING**  
Servicing while pressurized can cause severe injury  
**LOCK OUT SOURCE** and **RELIEVE PRESSURE** before servicing

CHS950022 <http://www.cemanet.org>

CHS950022

**WARNING**  
Moving equipment can cause severe injury  
**KEEP AWAY**

CHR931005 <http://www.cemanet.org>

CHR931005

**WARNING**  
Exposed conveyors and moving parts can cause severe injury  
**LOCK OUT POWER** before removing cover or servicing

CHR930010 <http://www.cemanet.org>

CHR930010

**WARNING**  
Servicing while pressurized can cause severe injury  
**LOCK OUT SOURCE** and **RELIEVE PRESSURE** before servicing

CHS950016 <http://www.cemanet.org>

CHS950016

**WARNING**  
Rotating shaft can cause severe injury  
Keep hair and loose clothing away

CHR951023 <http://www.cemanet.org>

CHR951023

**WARNING**  
Guard Removed  
Risk of severe injury  
**DO NOT OPERATE** Without guard

CHR000025 <http://www.cemanet.org>

CHR000025

**WARNING**  
Walking or standing on conveyor covers or gratings can cause severe injury  
**STAY OFF**

CHS991026 <http://www.cemanet.org>

CHS991026

**WARNING**  
Operating conveyor without linesshaft guard can cause severe injury  
**KEEP GUARD IN PLACE**

CHR050027 <http://www.cemanet.org>

CHR050027

**CAUTION**  
Insure skirting system is properly adjusted  
Failure to properly install, inspect, adjust, and maintain skirting system may result in spillage, dust, downtime, equipment damage, or personal injury

CHS060028 <http://www.cemanet.org>

CHS060028

**CAUTION**  
Insure belt cleaning and scraping system is properly adjusted  
Failure to properly install, inspect, adjust, and maintain this system may result in spillage, dust, downtime, equipment damage, or personal injury

CHS060029 <http://www.cemanet.org>

CHS060029

**CAUTION**  
Insure impact cradle is properly set  
Failure to properly install, inspect, adjust, and maintain this system may result in spillage, dust, downtime, equipment damage, or personal injury

CHS060030 <http://www.cemanet.org>

CHS060030

**CAUTION**  
Insure belt is properly tracking and aligned.  
Failure to properly install, inspect, adjust, and maintain the belt tracking and alignment system may result in spillage, dust, downtime, equipment damage, or personal injury

CHS060031 <http://www.cemanet.org>

CHS060031

**WARNING**  
Exposed conveyors and moving parts can cause severe injury  
**LOCK OUT POWER** before removing

CVS930010 <http://www.cemanet.org>

CVS930010

**WARNING**  
Exposed buckets and moving parts can cause severe injury  
**LOCK OUT POWER** before removing cover or servicing

CVS930012 <http://www.cemanet.org>

CVS930012

**WARNING**  
Exposed screw and moving parts can cause severe injury  
**LOCK OUT POWER** before removing cover or servicing

CVS930011 <http://www.cemanet.org>

CVS930011

**DANGER**  
Hazardous Condition  
Entry will result in severe injury or death  
**LOCK OUT POWER AND BLOCK HOIST** before servicing

CVR940019 <http://www.cemanet.org>

CVR940019

**WARNING**  
Exposed moving parts can cause severe injury  
**LOCK OUT POWER** before removing guard

CVS950020 <http://www.cemanet.org>

CVS950020

**CAUTION**  
Risk of Electrical Shock  
More than one disconnect switch may be required to de-energize the equipment before servicing

CVR950024 <http://www.cemanet.org>

CVR950024